

	R1LV0208BSA-5SI#B0
	Manufacturer Part Number: R1LV0208BSA-5SI#B0
	Manufacturer/Brand: Renesas Electronics America
	Part of Description: IC SRAM 2MBIT 55NS 32STSOP
	Datasheets:  R1LV0208BSA-5SI#B0.pdf
	RoHs Status:  Lead free / RoHS
	Stock Condition: Compliant New original, Stock Available.
	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS









Specifications

Part Number	R1LV0208BSA-5SI#B0
Manufacturer	Renesas Electronics America
Description	IC SRAM 2MBIT 55NS 32STSOP
Category	Integrated Circuits (ICs) > Memory
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Interface	Parallel
Package / Case	32-TFSOP (0.465", 11.80mm Width)
Supplier Device Package	32-sTSOP
Voltage - Supply	2.7 V ~ 3.6 V
Memory Type	Volatile
Speed	55ns
Memory Size	2Mb (256K x 8)
Memory Format	SRAM
Packaging	Tray

R1LV0208BSA-5SI#B0 is New Original in Stock, Search R1LV0208BSA-5SI#B0 Datasheets, PDF, Inventory at Y-IC.com Online, Order R1LV0208BSA-5SI#B0 Renesas Electronics America with warrantied and confidence. RFQ R1LV0208BSA-5SI#B0 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>R1LV0208BSA-5SI#B1 Renesas Electronics America IC SRAM 2MBIT 55NS 32STSOP</p>	 <p>R1LV0108ESN-7SR#S0 Renesas Electronics America IC SRAM 1MBIT 70NS 32SOP</p>	 <p>R1LV0216BSB-5SI Renesas Electronics America R1LV0216BSB-5SI RENESAS</p>	 <p>R1LV0108ESN-7SR#B0 Renesas Electronics America IC SRAM 1MBIT 70NS 32SOP</p>
 <p>R1LV0208BSA-5SI#S1 Renesas Electronics America IC SRAM 2MBIT 55NS 32TSOP</p>	 <p>R1LV0108ESN-7SI#S0 Renesas Electronics America IC SRAM 1MBIT 70NS 32SOP</p>	 <p>R1LV0208BSA-5SI#S0 Renesas Electronics America IC SRAM 2MBIT 55NS 32TSOP</p>	 <p>R1LV0108ESP-7SI RENESAS RENESAS SOP</p>

Hot Parts

More

- | | | | | |
|-------------------|---------------------|-----------------------|----------------------|----------------------|
| ⊛ 02013A5R6CAT2A | ↔ 12103C274MAT2A | ⇒ 18085C273JAT9A | D A8502KLPTR-T | ⇒ ATAR892U-076-TKQ19 |
| ⊣ BD135G-16-AA3-R | ⊛ BTS5180-2E | D C1005X7S0G225K050BC | ⇒ CD5C5200-HF | ⇒ CG0603MLA-14KE |
| ⊛ CL32A475KLULNNE | ⊣ CL32B475KBUYNNE | ⊛ CSD16409Q3. | ↔ CSD97370Q5M | ⇒ CY27C512-150JC |
| D D24N1400C | ⊛ DTA144EKT147 | ⊣ DWK2415D-3W | ⊛ GRM42A5C3F220JW01L | ⇒ HD6437044E41F |
| ⇒ HMHAA281R1 | ↔ HTT45F800KSC | ⊛ IRS2607DSTRPBF. | ⊣ IS45S16400F-7TLA1 | ⇒ L7805C-V |
| ↔ LMV772QMMX | ⇒ MAX483CSA-TG068 | D MAX821SUS-T | ⊛ MC9RS08KB12CFK | ⊣ MSD309PX-LF-SG |
| ⊛ NTD12N10-001 | D PI3B3257QE | ⇒ PMV130ENEA | ↔ PS2561-1V-M | ⇒ PS8740AQFN40GTR.B0 |
| ⊣ RP102Z151D-TR-F | ⊛ S-1711A2518-M6T1G | ↔ SKB30/06A1 | ⇒ SKMD100/02E | ⇒ SMCJ7.0A-E3/57T |
| ⊛ SN74LVC1G07DCKR | ⊣ SN74LVC2G32DCUR | ⊛ STD10NF06LT4 | D T599F11TEC | ⇒ TC1224-3.3VCT713 |
| ↔ TD60N12KOF | ⊛ TS250-130F-2 | ⊣ V48C5H100AL | ⊛ VND5E025ASTR | ⇒ Z8F021ASJ020SG |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited