


	<p>S-80841CLNB-B62T2U</p>
	<p>Manufacturer Part Number: S-80841CLNB-B62T2U</p>
	<p>Manufacturer/Brand: SII Semiconductor Corporation</p>
	<p>Part of Description: IC VOLT DETECTOR 4.1V SC-82AB</p>
	<p>Datasheets:  S-80841CLNB-B62T2U.pdf</p>
	<p>RoHS Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>

Specifications

Part Number	S-80841CLNB-B62T2U
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 4.1V SC-82AB
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-808xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-82A, SOT-343
Supplier Device Package	SC-82AB
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	4.1V
Packaging	Tape & Reel (TR)

S-80841CLNB-B62T2U is New Original in Stock, Search S-80841CLNB-B62T2U Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80841CLNB-B62T2U SII Semiconductor Corporation with warrantied and confidence. RFQ S-80841CLNB-B62T2U : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-80841ANUP-ED5-T2 SEIKO SEIKO SOT89</p>	 <p>S-80841ANNP-ED5-T2 SEIKO S-80841ANNP-ED5-T2 SEIKO</p>	 <p>S-80841CLPF-B62TFG SII Semiconductor Corporation IC VOLT DETECTOR 4.1V SNT-4A</p>	 <p>S-80841CLPF-B62TFU SII Semiconductor Corporation IC VOLT DETECTOR 4.1V SNT-4A</p>
 <p>S-80841CLNB-B62T2G SII Semiconductor Corporation IC VOLT DETECTOR 4.1V SC-82AB</p>	 <p>S-80841CLUA-B62-T2 SEIKO S-80841CLUA-B62-T2 SEIKO</p>	 <p>S-80841CLMC-B62T2G SII Semiconductor Corporation IC VOLT DETECTOR 4.1V SOT23-5</p>	 <p>S-80841CLUA-B62T2U SII Semiconductor Corporation IC VOLT DETECTOR 4.1V SOT89-3</p>

Hot Parts

More

- | | | | | |
|-------------------|-----------------|----------------------|---------------------|---------------------|
| 08053C333KAT2A | 12065A100DAT2A | 12102A820JAT2A | 2MBI300TE-060 | AD7683BCPZ |
| ALM-2812TR1G | AT807S09 | BYM300GB120DN2 | C3216C0G2W153K160AA | CC0402BRNPO9BN1R8 |
| CC1808JKNPOEBN180 | CIH10T1N5SNCS | DMC201010R | FDMS86101DC | GRM42-6B224K25NPT |
| HCPL-2630 | ICS574MLFT | IRFIBC40G | ISL84541CB-T | LM1236DEM/NA |
| LMV321A55X | LT1371CR | LTC1326CS8-2.5#TRPBF | LTC1843IS8#TRPBF | LTC6912CGN-1#TRPBF |
| M74HC51B1 | M74HCT574RM13TR | MAX4070ATA-T | MAX9669ETI-T | MC144111DW |
| MDD220-04N1 | MIC2040-1YM | MIC811SU | MK010A1-C | MUR20040 |
| N260CH32 | NTS0104GU12 | NX2124CSTR | PB10E-05-A | RJK1003DPP-E0 |
| SI4398DY-T1-E3 | SKD33/04 | SKT40/12 | SML4735-E3/61 | SP6205EM5-L-2-85/TR |
| SPX3940AM3-L-1-8 | TC1029EUATR | VI-2NO-EY | WG5025FR | ZXTEM322TA |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited