

 Not Actual Photo YIC International Co., Limited.	<p><b>02DZ3.3-Z</b></p> <p><b>Manufacturer Part Number:</b> <a href="#">02DZ3.3-Z</a></p> <p><b>Manufacturer/Brand:</b> TOSHIBA</p> <p><b>Part of Description:</b> TOSHIBA SOD323</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 42400 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	<p>Image may be representation. See specs for product details.</p>

### Specifications

Part Number	<a href="#">02DZ3.3-Z</a>
Manufacturer	TOSHIBA
Description	TOSHIBA SOD323
Category	<a href="#">Integrated Circuits (ICs) &gt; Specialized Hot ICs</a>
Part Status	42400 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	<a href="mailto:Info@Y-IC.com">Info@Y-IC.com</a>

02DZ3.3-Z is New Original in Stock, Search 02DZ3.3-Z Datasheets, PDF, Inventory at Y-IC.com Online, Order 02DZ3.3-Z with warranted and confidence. RFQ 02DZ3.3-Z : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

In:

 <b>02DZ3.0-X(TPH3,F)</b> TOSHIBA TOSHIBA 3.0V	 <b>02DZ3.3-X</b> TOSHIBA TOSHIBA SOD-323	 <b>02DZ3.6-X</b> TOSHIBA TOSHIBA 805	 <b>02DZ3.9-X</b> TOSHIBA TOSHIBA SOD323
 <b>02DZ3.3-Z(TPH3)</b> TOSHIBA TOSHIBA SOD-323	 <b>02DZ3.9-X(TPH3)</b> TOSHIBA TOSHIBA SOD-323	 <b>02DZ3.6-Z</b> TOSHIBA TOSHIBA SOD3230805-3.6V	 <b>02DZ3.0-X(TPH3)</b> TOSHIBA TOSHIBA 3.0V

### Hot Parts More

- |                         |                        |                        |                      |                      |
|-------------------------|------------------------|------------------------|----------------------|----------------------|
| ⊛ 06032U3R9CAT2A        | ↔ 18121C683KAT2A       | ⇒ A70P1200-4           | D ADG1633BCPZ        | ⇒ AP1506-50T5        |
| ↳ B39162-B9000-C710-S09 | ⊛ BAV16WS-7-F          | D BGB208A01            | ⇒ BQ27505YZGR-11     | ⇒ CC1210KX7RBBB332   |
| ⊛ CD4015BCN             | ↳ CGA5L2X5R1H474M160AA | ⊛ CGA5L3X8R2A334K160AD | ↔ DPX205850DT-9038A1 | ⇒ ESD5B5CL           |
| D F751A477MRC           | ⊛ FST3126QSC           | ↳ GCM1555C1H2R2CZ13D   | ⊛ GRM1885C1H1R0BZ01D | ⇒ HZD25-48S15        |
| ⇒ IRF6678TR1PBF         | ↔ KSD225AC3            | ⊛ LT1301CS8            | ↳ LT1739IFE          | ⇒ LTST-C190KFKT      |
| ↔ MAX213EEAI+T          | ⇒ MAX485EESA+T         | D MBCR10MH             | ⊛ MCC19-16io1        | ↳ MPC82E54AT2        |
| ⊛ PBMB200E6             | D PIC18LF13K22-I/SO    | ⇒ PKJ4618HEPI          | ↔ R400CH06CG         | ⇒ S-80129BLMC-JEOT2G |
| ↳ S-80830CNNB-B8P-T2    | ⊛ S1D13714B01C100      | ↔ SBR20A120CT          | ⇒ SKM100GAL128D      | ⇒ SM18MCR094         |
| ⊛ SM34CXC374            | ↳ SMF26A-E3-08         | ⊛ TA016TCM105KAR       | D TA78M06S           | ⇒ TL074IDRG4         |
| ↔ UMK212SD562JD-T       | ⊛ UNRF2AN00A           | ↳ USB82514AMR          | ⊛ V48B28T250A        | ⇒ V48C5H100BL2       |